

CONSTRUCTION EQUIPMENT SW1027835 STEFFY VOLVO ECR235E 314278 - REAR LEFT FINAL

Sample No: VCP419576

Oil Type: **GEAR OIL SAE 80W90** Job No: SW1027835 STEFFY

LUMUI	E INFORMATION	N		
				<u>.</u>
Sample Number		VCP419576	VCP406323	
Sample Date		16 Dec 2023	15 Jul 2023	
Machine Hours		2210	1700	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
OIL CON	IDITION			
Visc @ 40°C	cSt	145	<u> </u>	
VISC @ 40 C	CSL	145	172	
VOLVO				
CONTAI	MINATION			
Water	%	NEG	NEG	
Silicon	ppm	27	1 7	
Sodium	ppm	0	4	
Potassium	ppm	5	<1	
	PPIII		- 1	
VOLVO				
WEAR	METALS			
Iron	ppm	455	■325	
Copper	ppm	2	- <1	
Lead	ppm	0	0	
Tin	ppm	■ 0	0	
Aluminum	ppm	4	3	
Chromium	ppm	6	6	
Molybdenum	ppm	2	1	
Nickel	ppm	■0	- <1	
Titanium	ppm	<1	<1	
Silver	ppm	0	0	
Manganese	ppm	■ 4	4	
Vanadium	ppm	0	<1	
VOLVO	VIEC			
ADDITI	AT-7			
Calcium	ppm	21	7	
Magnesium	ppm	■8	- <1	
Zinc	ppm	■8	■28	
Phosphorus	ppm	504	493	
Barium	ppm	0	- <1	
-			0	



ARNOLD MACHINERY COMPANY 4323 EAST WINSLOW AVENUE

PHOENIX, AZ US 85040

Contact: RANDY PRZEKURAT randyp@arnoldmachinery.com

T:

F: (602)414-1904

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO6174 **Unique No:** 10805879 Signed: Sean Felton Report Date: 28 Dec 2023

46

Boron



CONSTRUCTION EQUIPMENT





