



CONSTRUCTION EQUIPMENT

X13758 VOLVO A25G 752427 - TRANSMISSION (AUTO)



Sample No: VCP400323
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No: X13758



SAMPLE INFORMATION

Sample Number	VCP400323	---	---	---
Sample Date	18 Dec 2023	---	---	---
Machine Hours	2536	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

SCOTT EQUIPMENT COMPANY LLC - Broussard
 100 IDA ROAD
 BROUSSARD, LA
 US 70518
 Contact: ADAM FEIRMAN
 afeirman@scottcompanies.com
 T: (337)837-2907
 F: (337)837-5116



OIL CONDITION

Visc @ 40°C	cSt	█ 28.6	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 10	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 4	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 48	---	---	---
Copper	ppm	█ 17	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 5	---	---	---
Aluminum	ppm	█ 26	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 2	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 90	---	---	---
Magnesium	ppm	█ 2	---	---	---
Zinc	ppm	0	---	---	---
Phosphorus	ppm	█ 203	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 82	---	---	---

Depot: VOLVO6241
Unique No: 10805901
Signed: Sean Felton
Report Date: 28 Dec 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

