



CONSTRUCTION EQUIPMENT

W08010166 HERC VOLVO L70H 624777 - DIESEL FUEL



Sample No: VCP407639
Oil Type: {unknown}
Job No: W08010166 HERC



SAMPLE INFORMATION

Sample Number	VCP407639	---	---	---
Sample Date	21 Dec 2023	---	---	---
Machine Hours	389	---	---	---
Sample Status	ABNORMAL	---	---	---

MCCLUNG-LOGAN EQUIPMENT CO - CHESAPEAKE
4112 HOLLAND BLVD
CHESAPEAKE, VA
US 23323
Contact: TOMMY GRIFFIN
tgriffin@mcllung-logan.com
T: (757)485-3314
F: (757)485-3415



FUEL CONDITION

Sulfur	ppm	0	---	---	---
Visc @ 40°C	cSt	2.37	---	---	---



CONTAMINATION

Water	%	0.042	---	---	---
Lead	ppm	0	---	---	---
Nickel	ppm	0	---	---	---
Aluminum	ppm	0	---	---	---
Vanadium	ppm	0	---	---	---
Silicon	ppm	0	---	---	---

Diagnosis

This is a baseline read-out on the submitted sample. We recommend you service and check the fuel filters for mucous-like deposits. Check with fuel supplier for biocides available to destroy the microorganisms in the fuel system. All metal levels are normal indicating no corrosion in the cooling system. Appearance is hazy. Excessive free water present. Moderate concentration of visible dirt/debris present in the fuel. The condition of the fuel is acceptable for the time in service.

Depot: VOLVO0264
Unique No: 10805946
Signed: Jonathan Hester
Report Date: 28 Dec 2023



CONSTRUCTION EQUIPMENT



GRAPHS

Pensky-Martens Flash Point (°C)

