



CONSTRUCTION EQUIPMENT

1379 SENNEBOGEN 835 835.0.2517 - FRONT RIGHT PLANETARY



Sample No: VCP442614
Oil Type: MOBIL 75W90
Job No: 1379



SAMPLE INFORMATION

Sample Number	VCP442614	---	---	---
Sample Date	14 Dec 2023	---	---	---
Machine Hours	6725	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

SIMS METAL
130 NORTH 12TH ST
SACRAMENTO, CA
US 95814
Contact: EVERT



OIL CONDITION

Visc @ 40°C	cSt	█ 132	---	---	---
-------------	-----	-------	-----	-----	-----

T: (916)769-7864
F:



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 2	---	---	---
Sodium	ppm	█ 3	---	---	---
Potassium	ppm	█ 0	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 111	---	---	---
Copper	ppm	█ 23	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 2	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	35	---	---	---
Magnesium	ppm	3	---	---	---
Zinc	ppm	34	---	---	---
Phosphorus	ppm	█ 1057	---	---	---
Barium	ppm	19	---	---	---
Boron	ppm	█ 161	---	---	---

Depot: SIMSACCA
Unique No: 10806345
Signed: Angela Borella
Report Date: 28 Dec 2023



CONSTRUCTION EQUIPMENT



GRAPHS

