



# CONSTRUCTION EQUIPMENT

D13105 VOLVO A40G 342238 - BOGIE/CENTER AXLE



**Sample No:** VCP429523  
**Oil Type:** VOLVO SUPER GEAR OIL 75W-80-GO102  
**Job No:** D13105



ARING EQUIPMENT COMPANY INC - MAIN (MILWAUKEE)  
13001 W SILVERE SPRING DR  
BUTLER, WI  
US 53007  
Contact: GLENN OTTENBACHER  
gottenbacher@aring.com  
T: (262)282-0715  
F: (262)781-5053



## SAMPLE INFORMATION

Sample Number	VCP429523	---	---	---
Sample Date	20 Dec 2023	---	---	---
Machine Hours	8747	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



## OIL CONDITION

Visc @ 40°C	cSt	■ 53.2	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 2	---	---	---
Sodium	ppm	■ 0	---	---	---
Potassium	ppm	■ 0	---	---	---



## WEAR METALS

Iron	ppm	■ 48	---	---	---
Copper	ppm	■ 0	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ <1	---	---	---
Aluminum	ppm	■ 0	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	■ 0	---	---	---
Nickel	ppm	■ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ <1	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	■ 14	---	---	---
Magnesium	ppm	■ <1	---	---	---
Zinc	ppm	■ 5	---	---	---
Phosphorus	ppm	■ 2252	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 269	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO0069  
**Unique No:** 10807054  
**Signed:** Jonathan Hester  
**Report Date:** 29 Dec 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

