



CONSTRUCTION EQUIPMENT

W08010130-3 VOLVO L60H 622631 - REAR AXLE



Sample No: VCP416866
Oil Type: VOLVO WB 102
Job No: W08010130-3



SAMPLE INFORMATION

Sample Number	VCP416866	---	---	---
Sample Date	27 Dec 2023	---	---	---
Machine Hours	2480	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

MCCLUNG-LOGAN EQUIPMENT CO - CHESAPEAKE
4112 HOLLAND BLVD
CHESAPEAKE, VA
US 23323
Contact: TOMMY GRIFFIN
tgriffin@mcclung-logan.com
T: (757)485-3314
F: (757)485-3415



OIL CONDITION

Visc @ 40°C	cSt	█42.7	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█13	---	---	---
Sodium	ppm	█0	---	---	---
Potassium	ppm	█2	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█48	---	---	---
Copper	ppm	█3	---	---	---
Lead	ppm	█0	---	---	---
Tin	ppm	█0	---	---	---
Aluminum	ppm	█2	---	---	---
Chromium	ppm	█1	---	---	---
Molybdenum	ppm	█<1	---	---	---
Nickel	ppm	█0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█2	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█3805	---	---	---
Magnesium	ppm	█12	---	---	---
Zinc	ppm	█1564	---	---	---
Phosphorus	ppm	█1338	---	---	---
Barium	ppm	█0	---	---	---
Boron	ppm	█141	---	---	---

Depot: VOLVO0264
Unique No: 10808080
Signed: Wes Davis
Report Date: 29 Dec 2023



CONSTRUCTION EQUIPMENT



GRAPHS

