

## CONSTRUCTION EQUIPMENT 24468 VOLVO A30 753397 - REAR AXLE



Sample No: VCP429004

Oil Type: VOLVO SUPER GEAR OIL 75W-80-GO102

**Job No:** 24468

VOLVO	INFORMATIO	N		
	INFORMATIO			_
Sample Number		VCP429004	 	
Sample Date		22 Dec 2023	 	
Machine Hours		569	 	
Oil Hours		500	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	NITION			
Visc @ 40°C	cSt	<b>87.0</b>	 	
VOLVO				
CONTAN	IINATION			
Water	%	NEG	 	
Silicon		NEG ■7	 	
Sodium	ppm	_	 	
	ppm	3		
Potassium	ppm	<b>■</b> 6	 	
VOLVO				
WEAR M	IETALS			
Iron	ppm	<b>258</b>	 	
Copper	ppm	14	 	
Lead	ppm	<1	 	
Tin	ppm	<1	 	
Aluminum	ppm	<1	 	
Chromium	ppm	<b>6</b>	 	
Molybdenum	ppm	<b>4</b>	 	
Nickel	ppm	<b>3</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>12</b>	 	
Vanadium	ppm	<1	 	
	PPIII	.,		
VOLVO			 	
ADDITIV	EZ			
Calcium	ppm	<b>940</b>	 	
Magnesium	ppm	<b>6</b>	 	
Zinc	ppm	<b>419</b>	 	
Phosphorus	ppm	<b>1538</b>	 	
Barium	ppm	<b>4</b>	 	
Boron	ppm	<b>270</b>	 	



218 - ASCENDUM MACHINERY INC - N. CHARLESTON 7235 CROSS COUNTRY RD. NORTH CHARLESTON, SC US 29418 Contact: MATT MITCHAM matt.mitcham@ascendummachinery.com T: F: (843)414-1129

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO3387Unique No:10809069Signed:Don BaldridgeReport Date:03 Jan 2024



## **CONSTRUCTION EQUIPMENT**





