

## CONSTRUCTION EQUIPMENT 24468 VOLVO A30 753397 - FRONT AXLE



Sample No: VCP429010

Oil Type: VOLVO SUPER GEAR OIL 75W-80-GO102

**Job No:** 24468

SAMPLE	INFORMATIO	N		
Sample Number		VCP429010	 	
·				
Sample Date		22 Dec 2023	 	
Machine Hours		569	 	
Oil Hours		500	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>88.1</b>	 	
VOLVO	AIN A TION			
LUNIAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	<b>6</b>	 	
Sodium	ppm	<b>■</b> 3	 	
Potassium	ppm	<b>6</b>	 	
VOLVO	AETAL C			
WEAR N	AE I ALS			
Iron	ppm	■293	 	
Copper	ppm	■17	 	
Lead	ppm	<b>■</b> <1	 	
Tin	ppm	<b>■&lt;1</b>	 	
Aluminum	ppm	<b>■&lt;1</b>	 	
Chromium	ppm	<b>6</b>	 	
Molybdenum	ppm	<b>■8</b>	 	
Nickel	ppm	<b>■</b> 3	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>12</b>	 	
Vanadium	ppm	<1	 	
ADDITIV	/FS			
_				
Calcium	ppm	<b>803</b>	 	
Magnesium	ppm	<b>5</b>	 	
Zinc	ppm	■366	 	
Phosphorus	ppm	■1500	 	
Barium	ppm	■5	 	
Boron	ppm	<b>255</b>	 	



218 - ASCENDUM MACHINERY INC - N. CHARLESTON 7235 CROSS COUNTRY RD. NORTH CHARLESTON, SC US 29418 Contact: MATT MITCHAM matt.mitcham@ascendummachinery.com T: F: (843)414-1129

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO3387Unique No:10809074Signed:Don BaldridgeReport Date:03 Jan 2024



## **CONSTRUCTION EQUIPMENT**





## GRAPHS

