

CONSTRUCTION EQUIPMENT VOLVO L110H 05631970 - REAR AXLE



Sample No: VCP439470
Oil Type: VOLVO WB 101

Job No:

VOLVO	INFORMATION			
	INFURMATION			
Sample Number		VCP439470	VCP294645	
Sample Date		27 Dec 2023	08 Dec 2020	
Machine Hours		4896	1155	
Oil Hours		0	0	
Oil Changed		Changed	Not Changd	
Sample Status		ABNORMAL	NORMAL	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	43.1	39.5	
VISC @ 40 C	CSI	43. 1	39.3	
VOLVO				
CONTAN	MINATION			
Water	%	NEG	NEG	
Silicon	ppm	1 5	1 0	
Sodium	ppm	■0	7	
Potassium	ppm	■3	2	
	I. I.			
VOLVO	ACTAL C			
WEAR N	UF LATZ			
Iron	ppm	48	267	
Copper	ppm	■<1	1	
Lead	ppm	■<1	0	
Tin	ppm	■ <1	0	
Aluminum	ppm	2	□ 0	
Chromium	ppm	■<1	6	
Molybdenum	ppm	2	13	
Nickel	ppm	■<1	1	
Titanium	ppm	<1	0	
Silver	ppm	0	0	
Manganese	ppm	2	11	
Vanadium	ppm	0	0	
VOLVO				
ADDITIV	/FS			
Calcium	ppm	4368	4008	
Magnesium	ppm	16	13	
Zinc	ppm	1635	1558	
Phosphorus	ррт	1284	1305	
Barium		1204	0	
	ppm	145	129	
Boron	ppm	145	129	



CITY CARTING221 OLD GATE LN

221 OLD GATE LN
MILFORD, CT
US 06460
Contact: TAVINS BANKS
tavins@citycart.net
T: (203)223-3885
F:

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The condition of the oil is acceptable for the time in service.

Depot:CITMILCONUnique No:10820282Signed:Jonathan HesterReport Date:10 Jan 2024



CONSTRUCTION EQUIPMENT





