



CONSTRUCTION EQUIPMENT

SWO-068628 VOLVO A45G 353092 - COOLANT



Sample No: VCP447540
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: SWO-068628



SAMPLE INFORMATION

Sample Number	VCP447540	VCP432850	VCP407524	VCP395495
Sample Date	03 Jan 2024	19 Sep 2023	09 Jun 2023	23 Feb 2023
Machine Hours	2545	2012	1497	1000
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL



COOLANT CONDITION

pH	Scale 0-14	7.32	7.44	7.53	7.99
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	NT	NT	NT
Percentage Glycol	%	44.2	44.1	44.1	43.9
Freezing Point	°C	-21	-21	-21	-19



CONTAMINATION

Coolant Appearance	normal	normal	normal	normal
Coolant Color	Yllow	Yllow	Yllow	Yllow

SAIIA CONSTRUCTION LLC

4400 LEWISBURG RD
BIRMINGHAM, AL
US 35207

Contact: STEPHANI BRITTON
sbritton@saiia.com;doug.bogart@wearcheck.com
T: (205)943-2268
F: (205)943-2269

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: SAIBIR
Unique No: 10820475
Signed: Jonathan Hester
Report Date: 10 Jan 2024




CONSTRUCTION EQUIPMENT




VOLVO GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

