

CONSTRUCTION EQUIPMENT VOLVO EC250EL 314086 - COOLANT



Sample No: VCP434057

Oil Type: VOLVO COOLANT VCS (YELLOW)

Job No:

SAMPLE II	NFORMATION			
Sample Number	-	VCP434057	VCP407670	
Sample Date		21 Dec 2023	24 May 2023	
Machine Hours		4629	4006	
Sample Status		NORMAL	NORMAL	
COOLANT	CONDITION			
рН	Scale 0-14	7.28	7.36	
Reserve Alkalinity	Scale 0-20			
Nitrites	ppm	■ NT	■ NT	
Percentage Glycol	%	50.3	49.8	
Freezing Point	°C	-35	-33	
CONTAMIN	NATION			
Coolant Appearance		normal	normal	
Coolant Color		Yllow	Yllow	



CITY CARTING
221 OLD GATE LN
MILFORD, CT
US 06460
Contact: TAVINS BANKS
tavins@citycart.net
T: (203)223-3885
F:

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:CITMILCONUnique No:10820477Signed:Jonathan HesterReport Date:10 Jan 2024



CONSTRUCTION EQUIPMENT





GRAPHS

