

CONSTRUCTION EQUIPMENT
W07014038-2 WATERFRO TAKEUCHI TB230 130009 141 - REAR

Sample No: VCP447813

Oil Type: **GEAR OIL SAE 85W90**

Job No: W07014038-2 WATERFRO

VOLVO	LINEODMATION	J		
	E INFORMATION	\ <u>.</u>		
Sample Number		VCP447813	 	
Sample Date		28 Dec 2023	 	
Machine Hours		122	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		ABNORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	124	 	
		_		
VOLVO	MINISTICAL .			
LUNIAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	<u></u> 82	 	
Sodium	ppm	6	 	
Potassium	ppm	■ 4	 	
WEAR N	AETAL C			
_	AE I WE?			
Iron	ppm	191	 	
Copper	ppm	■ 2	 	
Lead	ppm	■ <1	 	
Tin	ppm	■ <1	 	
Aluminum	ppm	1 0	 	
Chromium	ppm	■15	 	
Molybdenum	ppm	1	 	
Nickel	ppm	■1	 	
Titanium	ppm	2	 	
Silver	ppm	0	 	
Manganese	ppm	11	 	
Vanadium	ppm	0	 	
ADDITIV	VES			
Calcium	ppm	63	 	
Magnesium	ppm	■3	 	
Zinc	ppm	105	 	
Phosphorus	ppm	471	 	
Barium	ppm	■17	 	
Boron	ppm	■53	 	
	P P			



MCCLUNG-LOGAN EQUIPMENT CO - RICHMOND 1345 MOUNTAIN ROAD GLEN ALLEN, VA US 23060 Contact: KYLE RATLIFFE KRATLIFFE@MCCLUNG-LOGAN.COM F: (804)266-1611

Diagnosis

We advise that you check all areas where dirt can enter the system. The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. Metal levels are typical for a new component breaking in. Elemental levels of silicon (Si) and aluminum (Al) indicate alumina-silicate (coarse dirt) ingress. The condition of the oil is acceptable for the time in service.

Depot: VOLVO8882 **Unique No:** 10821027 Signed: Sean Felton Report Date: 10 Jan 2024



CONSTRUCTION EQUIPMENT





