



CONSTRUCTION EQUIPMENT

658790 JMH VOLVO A30G 752679 - FRONT AXLE



Sample No: VCP437647
Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5
Job No: 658790 JMH



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
 9601 BOGGY CREEK RD
 ORLANDO, FL
 US 32824
 Contact: Robert LaPlante
 robert.laplante@altg.com
 T: (407)508-9736
 F: (407)659-8720



SAMPLE INFORMATION

Sample Number	VCP437647	---	---	---
Sample Date	03 Jan 2024	---	---	---
Machine Hours	2060	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	■ 59.4	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	■ NEG	---	---	---
Silicon	ppm	■ 2	---	---	---
Sodium	ppm	■ 2	---	---	---
Potassium	ppm	■ <1	---	---	---



WEAR METALS

Iron	ppm	■ 160	---	---	---
Copper	ppm	■ 11	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ <1	---	---	---
Aluminum	ppm	■ 0	---	---	---
Chromium	ppm	■ 2	---	---	---
Molybdenum	ppm	■ 3	---	---	---
Nickel	ppm	■ 1	---	---	---
Titanium	ppm	■ 0	---	---	---
Silver	ppm	■ 0	---	---	---
Manganese	ppm	■ 4	---	---	---
Vanadium	ppm	■ 0	---	---	---



ADDITIVES

Calcium	ppm	■ 203	---	---	---
Magnesium	ppm	■ 1	---	---	---
Zinc	ppm	■ 90	---	---	---
Phosphorus	ppm	■ 1960	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 245	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0096
Unique No: 10821572
Signed: Sean Felton
Report Date: 10 Jan 2024



CONSTRUCTION EQUIPMENT



GRAPHS

