



CONSTRUCTION EQUIPMENT

VOLVO A40G 342685 - FRONT AXLE



Sample No: VCP0008136
Oil Type: GEAR OIL SAE 75W90
Job No:



SAMPLE INFORMATION

Sample Number	VCP0008136	---	---	---
Sample Date	05 Jan 2024	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	N/A	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT COMPANY
 8750 PHILIPS HWY
 JACKSONVILLE, FL
 US 32256
 Contact: TECHNICIAN ACCOUNT
 catherine.anastasio@wearcheck.com
 T:
 F: (904)737-1260

OIL CONDITION

Visc @ 40°C	cSt	■ 99.6	---	---	---
-------------	-----	--------	-----	-----	-----

CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 4	---	---	---
Sodium	ppm	■ 1	---	---	---
Potassium	ppm	■ 0	---	---	---

WEAR METALS

Iron	ppm	■ 137	---	---	---
Copper	ppm	■ < 1	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ < 1	---	---	---
Aluminum	ppm	■ 0	---	---	---
Chromium	ppm	■ 2	---	---	---
Molybdenum	ppm	■ 2	---	---	---
Nickel	ppm	■ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 4	---	---	---
Vanadium	ppm	0	---	---	---

ADDITIVES

Calcium	ppm	■ 38	---	---	---
Magnesium	ppm	■ 10	---	---	---
Zinc	ppm	■ 18	---	---	---
Phosphorus	ppm	639	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 84	---	---	---

Diagnosis
 Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 75W90. Please confirm.
 All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0092
Unique No: 10821602
Signed: Wes Davis
Report Date: 10 Jan 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

