



CONSTRUCTION EQUIPMENT

646159 DIPRO CATERPILLAR 972 2686 - COOLANT



Sample No: VCP452309
Oil Type: CAT EXTENDED LIFE COOLANT (ELC)
Job No: 646159 DIPRO



SAMPLE INFORMATION

Sample Number	VCP452309	---	---	---
Sample Date	28 Dec 2023	---	---	---
Machine Hours	12902	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT COMPANY - METRO WEST
56195 PONTIAC TRAIL
NEW HUDSON, MI
US 48165
Contact: PAUL CONZ
paul.conz@altg.com
T: (313)348-8861
F: (248)356-2029



COOLANT CONDITION

pH	Scale 0-14	■ 7.81	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 52.0	---	---	---
Freezing Point	°C	■ -40	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Red	---	---	---

Depot: VOLVO2990
Unique No: 10823128
Signed: Jonathan Hester
Report Date: 12 Jan 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

