



CONSTRUCTION EQUIPMENT

X11025 VEOLIA VOLVO EC220EL 31113 - COOLANT



Sample No: VCP449110
Oil Type: HYBRID (HOAT) COOLANT
Job No: X11025 VEOLIA



SAMPLE INFORMATION

Sample Number	VCP449110	---	---	---
Sample Date	04 Jan 2024	---	---	---
Machine Hours	7916	---	---	---
Sample Status	NORMAL	---	---	---

SCOTT EQUIPMENT COMPANY LLC - Texarkana
5401 SANDERSON LANE
TEXARKANA, AR
US 71854
Contact: JAMES DOSS
jdoss@scottcompanies.com
T:
F:



COOLANT CONDITION

pH	Scale 0-14	■ 8.45	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 49.8	---	---	---
Freezing Point	°C	■ -33	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

Depot: VOLVO1034
Unique No: 10829952
Signed: Jonathan Hester
Report Date: 15 Jan 2024



CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

