

CONSTRUCTION EQUIPMENT
SWA443779 TAKEUCHI TL 10V2 410004617 - HYDRAULIC SYSTE

Sample No: VCP441332

Oil Type: MOBIL 1 SUPER 46

Job No: SWA443779

CAMDICIN	NFORMATION				
Sample Number	IFURMATION	VCP441332	VCP420587		
Sample Date		10 Jan 2024	03 Jul 2023		
Machine Hours		0	1060		
Oil Hours		0	0		
Oil Changed		N/A	Not Changd		
Sample Status		NORMAL	ATTENTION		
OIL CONDI	TION				
Visc @ 40°C	cSt	48.6	■49.4		
Acid Number (AN)	mg KOH/g	■0.66	□ 0.79		
CONTAMINATION					

CONTAMINATION					
%	NEG	NEG			
	1939	▲ 8635			
	90	▲ 1714			
	6	4 2			
	18/14/10	20/18/13			
ppm	5	6			
ppm	2	2			
ppm	■ 0	- <1			
	ppm ppm	% NEG 1939 90 6 18/14/10 ppm 5 ppm 2	% NEG NEG 1939	% NEG NEG 1939	

WEAR	METALS			
Iron	ppm	■ 9	■8	
Copper	ppm	26	2 3	
Lead	ppm	2	2	
Tin	ppm	■0	- <1	
Aluminum	ppm	1	4	
Chromium	ppm	■0	- <1	
Molybdenum	ppm	17	1 9	
Nickel	ppm	■0	0	
Titanium	ppm	0	<1	
Silver	ppm	0	0	
Manganese	ppm	0	< 1	
Vanadium	ppm	0	0	

ADDITION						
Calcium	ppm	2688	■2981			
Magnesium	ppm	46	5 1			
Zinc	ppm	690	754			
Phosphorus	ppm	556	588			
Barium	ppm	0	0			
Boron	ppm	42	4 4			



ALTA EQUIPMENT COMPANY

5151 DR MARTIN LUTHER KING BLVD FORT MYERS, FL US 33905 Contact: TODD LARK tlark@altaequipfl.com

T:

F: (239)481-3302

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot: VOLVO0090 **Unique No:** 10830629 Signed: Wes Davis Report Date: 15 Jan 2024



CONSTRUCTION EQUIPMENT





GRAPHS

