

CONSTRUCTION EQUIPMENT VOLVO EC350EL 314575 - COOLANT



Sample No: VCP439467

Oil Type: VOLVO COOLANT VCS (YELLOW)

Job No:

SAMPLE I	FORMATION				
Sample Number		VCP439467	VCP424483	 	
Sample Date		10 Jan 2024	30 Sep 2023	 	
Machine Hours		1057	586	 	
Sample Status		NORMAL	NORMAL	 	
COOLANT	CONDITION				
рН	Scale 0-14	7.23	7.70	 	
Reserve Alkalinity	Scale 0-20			 	
Nitrites	ppm	NT NT	NT	 	
Percentage Glycol	%	47.5	47.6	 	
Freezing Point	°C	-28	-28	 	
	ATION				
Coolant Appearance	-	normal	normal	 	
Coolant Color		Yllow	Yllow	 	



CITY CARTING

221 OLD GATE LN MILFORD, CT US 06460 Contact: TAVINS BANKS tavins@citycart.net T: (203)223-3885 F:

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot:CITMILCONUnique No:10834634Signed:Jonathan HesterReport Date:19 Jan 2024


CONSTRUCTION EQUIPMENT



GRAPHS

Iron/Tin/Silver

VOLVO



Report Id: CITMILCON [WUSCAR] 06063252 (Generated: 01/19/2024 14:45:48) Rev: 1

Contact/Location: TAVINS BANKS - CITMILCON