




# CONSTRUCTION EQUIPMENT

## SENNEBOGEN 870M 870.0.345 - DIESEL ENGINE



**Sample No:** VCP431376  
**Oil Type:** VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3  
**Job No:**



### SAMPLE INFORMATION

Sample Number	<b>VCP431376</b>	VCP177178	---	---
Sample Date	<b>09 Jan 2024</b>	28 Nov 2016	---	---
Machine Hours	<b>17500</b>	8559	---	---
Oil Hours	<b>500</b>	0	---	---
Oil Changed	<b>Changed</b>	Changed	---	---
Sample Status	<b>NORMAL</b>	NORMAL	---	---

**DONJON MARINE**  
 100 CENTRAL AVE  
 HILLSIDE, NJ  
 US 07205  
 Contact:



### OIL CONDITION

Visc @ 100°C	cSt	<b>15.6</b>	16.26	---	---
Base Number (BN)	mg KOH/g	<b>8.5</b>	---	---	---
Oxidation (PA)	%	<b>126</b>	92	---	---

T: (908)964-8812  
 F:

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.



### CONTAMINATION

Water	%	<b>NEG</b>	NEG	---	---
Soot %	%	<b>0.6</b>	0.3	---	---
Nitration (PA)	%	<b>115</b>	92	---	---
Sulfation (PA)	%	<b>82</b>	66	---	---
Glycol	%	<b>NEG</b>	NEG	---	---
Fuel	%	<b>&lt;1.0</b>	<1.0	---	---
Silicon	ppm	<b>9</b>	5	---	---
Sodium	ppm	<b>0</b>	5	---	---
Potassium	ppm	<b>2</b>	2	---	---



### WEAR METALS

Iron	ppm	<b>55</b>	28	---	---
Copper	ppm	<b>8</b>	7	---	---
Lead	ppm	<b>12</b>	8	---	---
Tin	ppm	<b>1</b>	2	---	---
Aluminum	ppm	<b>2</b>	2	---	---
Chromium	ppm	<b>1</b>	1	---	---
Molybdenum	ppm	<b>77</b>	83	---	---
Nickel	ppm	<b>0</b>	<1	---	---
Titanium	ppm	<b>0</b>	0	---	---
Silver	ppm	<b>0</b>	0	---	---
Manganese	ppm	<b>0</b>	<1	---	---
Vanadium	ppm	<b>0</b>	0	---	---



### ADDITIVES

Calcium	ppm	<b>1373</b>	2430	---	---
Magnesium	ppm	<b>1261</b>	563	---	---
Zinc	ppm	<b>1605</b>	1482	---	---
Phosphorus	ppm	<b>1181</b>	1238	---	---
Barium	ppm	<b>3</b>	0	---	---
Boron	ppm	<b>3</b>	120	---	---

**Depot:** DONHILNJ  
**Unique No:** 10835345  
**Signed:** Don Baldrige  
**Report Date:** 20 Jan 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

