



CONSTRUCTION EQUIPMENT

0336 VOLVO L260 1358 - FRONT AXLE



Sample No: VCP438980
Oil Type: VOLVO WET BRAKE TRANSAXLE OIL
Job No: 0336



SAMPLE INFORMATION

Sample Number	VCP438980	---	---	---
Sample Date	15 Jan 2024	---	---	---
Machine Hours	1051	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
 8418 PALM RIVER ROAD
 TAMPA, FL
 US 33619
 Contact: KENNY HANEY
 khaney@flaglerce.com
 T: (813)630-0077
 F: (813)630-2233



OIL CONDITION

Visc @ 40°C	cSt	█41.4	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█12	---	---	---
Sodium	ppm	█0	---	---	---
Potassium	ppm	█4	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█74	---	---	---
Copper	ppm	█3	---	---	---
Lead	ppm	█0	---	---	---
Tin	ppm	█0	---	---	---
Aluminum	ppm	█2	---	---	---
Chromium	ppm	█1	---	---	---
Molybdenum	ppm	█1	---	---	---
Nickel	ppm	█0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█3	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█3786	---	---	---
Magnesium	ppm	█8	---	---	---
Zinc	ppm	█1691	---	---	---
Phosphorus	ppm	█1244	---	---	---
Barium	ppm	█3	---	---	---
Boron	ppm	█146	---	---	---

Depot: VOLVO0093
Unique No: 10835979
Signed: Wes Davis
Report Date: 19 Jan 2024



CONSTRUCTION EQUIPMENT



GRAPHS

