VOLVO

CONSTRUCTION EQUIPMENT CMC SENNEBOGEN 850 850.0.3186 - REAR AXLE



Sample No: VCP438014

Oil Type:	VOLVO PREMIUM GEAR OIL 80W-90 GL-5
Job No:	СМС

SAMPLE INFORMATION VCP438014 Sample Number Sample Date 02 Jan 2024 Machine Hours 1899 Oil Hours 1000 Oil Changed Changed NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 143 CONTAMINATION Water % NEG Silicon ppm 3 Sodium 0 🔲 ppm Potassium ppm 1 WEAR METALS Iron ppm 25



vanadium

ADDITIV	/ES			
Calcium	ppm	30	 	
Magnesium	ppm	10	 	
Zinc	ppm	0	 	
Phosphorus	ppm	991	 	
Barium	ppm	3	 	
Boron	ppm	36	 	



GREEN MACHINE SERVICES LLC

13 SPYROS DRIVE SOUTH AMBOY, NJ US 08879 Contact: JOE GRZANKOWSKI JOE@GREENMSRV.COM T: (732)673-5920 F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.


Depot:	GRESOUNJ
Unique No:	10835985
Signed:	Don Baldridge
Report Date:	21 Jan 2024

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: GRESOUNJ [WUSCAR] 06064603 (Generated: 01/21/2024 13:18:11) Rev: 1

Contact/Location: JOE GRZANKOWSKI - GRESOUNJ