

# CONSTRUCTION EQUIPMENT 659478 VOLVO A40G 315157 - WET DISC BRAKE



Sample No: VCP437459

Oil Type: VOLVO SUPER WET BRAKE TRANSAXLE OIL WB102

**Job No:** 659478

VOLVO	INCODMATION			
	INFORMATION			
Sample Number		VCP437459	 	
Sample Date		11 Jan 2024	 	
Machine Hours		2059	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	<b>40.7</b>	 	
VISC @ 40 C	CSL	<b>4</b> 0.7	 	
VOLVO				
CONTAM	INATION			
Water	%	NEG	 	
Silicon	ppm	<b>21</b>	 	
Sodium	ppm	<b>6</b>	 	
Potassium	ppm	<b>2</b>	 	
VOLVO WEAD N	IETAL C			
WEAR M	IETAL2			
Iron	ppm	■ 20	 	
Copper	ppm	<u> </u>	 	
Lead	ppm	<b>0</b>	 	
Tin	ppm	■0	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>■&lt;1</b>	 	
Molybdenum	ppm	<b>0</b>	 	
Nickel	ppm	<b>6</b>	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b></b>	 	
Vanadium	ppm	0	 	
VOLVO				
ADDITIV	IES			
Calcium	ppm	<b>□</b> 3622	 	
Magnesium	ppm	<b>■</b> 7	 	
Zinc	ppm	<b>1599</b>	 	
Phosphorus	ppm	<b>1399 1264</b>	 	
Barium	ppm	<b>3</b>	 	
Boron	ppm	<b>131</b>	 	
20.011	PPIII			



#### JON M HALL COMPANY

1920 BOOTHE CIRCLE SUITE 110 LONGWOOD, FL US 32750

Contact: SERVICE MANAGER

T: (407)215-0410 F:

### Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. The copper level is abnormal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:JONLONUnique No:10835997Signed:Don BaldridgeReport Date:21 Jan 2024



## **CONSTRUCTION EQUIPMENT**





