



CONSTRUCTION EQUIPMENT

A11864 ALPHA VOLVO EC160E 314175 - REAR RIGHT FINAL DRIVE



Sample No: VCP439493
Oil Type: MOBIL MOBILUBE HD 80W90
Job No: A11864 ALPHA



HOFFMAN EQUIPMENT - LIONVILLE
 120 GORDON DRIVE
 LIONVILLE, PA
 US 19341
 Contact: JIM FEHR
 jim.fehr@hoffmanequip.com
 T: (610)363-9200
 F: (610)594-0829

SAMPLE INFORMATION

Sample Number	VCP439493	VCP425967	VCP399914	VCP365728
Sample Date	12 Jan 2024	16 Aug 2023	02 Mar 2023	01 Dec 2022
Machine Hours	6540	5360	4350	3841
Oil Hours	1000	1000	1500	0
Oil Changed	Changed	Not Changd	Changed	Not Changd
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

OIL CONDITION

Visc @ 40°C	cSt	321	323	296	298
-------------	-----	------------	-----	-----	-----

CONTAMINATION

Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	2	1	2	2
Sodium	ppm	<1	0	0	0
Potassium	ppm	3	0	2	0

WEAR METALS

Iron	ppm	13	12	35	32
Copper	ppm	0	0	<1	<1
Lead	ppm	<1	0	0	0
Tin	ppm	0	<1	0	0
Aluminum	ppm	<1	1	1	2
Chromium	ppm	0	<1	<1	<1
Molybdenum	ppm	0	0	<1	<1
Nickel	ppm	0	0	0	<1
Titanium	ppm	0	0	0	0
Silver	ppm	0	0	0	0
Manganese	ppm	<1	<1	<1	<1
Vanadium	ppm	0	0	0	0

ADDITIVES

Calcium	ppm	40	8	12	4
Magnesium	ppm	2	1	1	<1
Zinc	ppm	8	2	10	7
Phosphorus	ppm	813	747	880	814
Barium	ppm	<1	0	0	0
Boron	ppm	23	26	135	143

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO8879
Unique No: 10836568
Signed: Sean Felton
Report Date: 22 Jan 2024



CONSTRUCTION EQUIPMENT



GRAPHS

