



# CONSTRUCTION EQUIPMENT

## VOLVO L30G 3224032 - RESERVOIR ANTI-FREEZE



**Sample No:** VCP0008159  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP0008159	---	---	---
Sample Date	17 Jan 2024	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Changd	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA EQUIPMENT COMPANY**  
 8750 PHILIPS HWY  
 JACKSONVILLE, FL  
 US 32256  
 Contact: TECHNICIAN ACCOUNT  
 catherine.anastasio@wearcheck.com  
 T:  
 F: (904)737-1260



### CONTAMINATION

Water	%	NEG	---	---	---
-------	---	-----	-----	-----	-----

### Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the anti-freeze. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

**Depot:** VOLVO0092  
**Unique No:** 10842743  
**Signed:** Doug Bogart  
**Report Date:** 05 Feb 2024



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

