



CONSTRUCTION EQUIPMENT

7198 IMERYS VOLVO A30G 742632 - REAR AXLE



Sample No: VCP437786
Oil Type: VOLVO API GL-5 SAE 75W90
Job No: 7198 IMERYS



SAMPLE INFORMATION

Sample Number	VCP437786	VCP319994	---	---
Sample Date	11 Dec 2023	28 Mar 2022	---	---
Machine Hours	4084	2052	---	---
Oil Hours	0	0	---	---
Oil Changed	Changed	Changed	---	---
Sample Status	NORMAL	ATTENTION	---	---

364 - ASCENDUM MACHINERY INC - MACON
 4807 HARRISON RD
 MACON, GA
 US 31206
 Contact: HALIE BAKER
 halie.baker@ascendummachinery.com
 T:
 F: (478)200-5859



OIL CONDITION

Visc @ 40°C	cSt	152	▲ 56.5	---	---
-------------	-----	------------	--------	-----	-----



CONTAMINATION

Water	%	NEG	NEG	---	---
Silicon	ppm	4	5	---	---
Sodium	ppm	1	6	---	---
Potassium	ppm	0	1	---	---



WEAR METALS

Iron	ppm	80	305	---	---
Copper	ppm	5	34	---	---
Lead	ppm	0	<1	---	---
Tin	ppm	<1	2	---	---
Aluminum	ppm	0	<1	---	---
Chromium	ppm	<1	6	---	---
Molybdenum	ppm	<1	7	---	---
Nickel	ppm	0	2	---	---
Titanium	ppm	<1	<1	---	---
Silver	ppm	0	5	---	---
Manganese	ppm	2	12	---	---
Vanadium	ppm	<1	0	---	---



ADDITIVES

Calcium	ppm	108	880	---	---
Magnesium	ppm	0	2	---	---
Zinc	ppm	40	335	---	---
Phosphorus	ppm	1229	1446	---	---
Barium	ppm	0	0	---	---
Boron	ppm	236	175	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: ASCMAC
Unique No: 10844633
Signed: Don Baldrige
Report Date: 24 Jan 2024



CONSTRUCTION EQUIPMENT



GRAPHS

