## CONSTRUCTION EQUIPMENT 7228 IMERYS REFRAC VOLVO A30G 742629 - BRAKE

VOLVO SUPER WET BRAKE TRANSAXLE OIL WB102



## Sample No: VCP449009

**Oil Type:** 

Barium

Boron

VOLVO

On Type:	VOLVO SUPER WET BRAKE TRANSAXLE OIL WETUZ					
Job No:	7228 IMERYS REFRAC					
SAMPL	E INFORMATION	N				
Sample Number		VCP449009				
Sample Date		02 Jan 2024				364 - ASCENDUM MACHINERY INC - MACON
Machine Hours		3979				4807 HARRISON RD
Oil Hours		0				MACON, GA
Oil Changed		Changed				US 31206
Sample Status		ABNORMAL				Contact: HALIE BAKER halie.baker@ascendummachinery.com
VOLVO						T:
V OIL CON				_		F: (478)200-5859
Visc @ 40°C	cSt	39.6				
VOLVO						Diagnosis
CONTA	MINATION					-
Water	%	NEG				The oil change at the time of sampling has been noted. No
Silicon	ppm	21				corrective action is recommended at
Sodium	ppm	6				this time. Resample at the next
Potassium	ppm					service interval to monitor.The
						copper level is abnormal. All other
VOLVO	METALS					component wear rates are normal.
	METALS					There is no indication of any contamination in the oil. The
Iron	ppm	52				condition of the oil is acceptable for
Copper	ppm	▲ 383				the time in service.
Lead	ppm	■4				
Tin	ppm					
Aluminum	ppm	□7				
Chromium	ppm					
Molybdenum	ppm	2				
Nickel	ppm	∎1				
Titanium	ppm	<1				
Silver	ppm	0				
Manganese	ppm	2				
Vanadium	ppm	<1				-
ADDITI	VES					
Calcium	ppm	2901				
Magnesium	ppm	5				
Zinc	ppm	1204				
Phosphorus	ppm	<b>1200</b>				
Dentria		- 1				

Depot:ASCMACUnique No:10844635Signed:Don BaldridgeReport Date:24 Jan 2024

1

92

ppm


ppm

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Contact/Location: ` - HALIE BAKER - ASCMAC