



# CONSTRUCTION EQUIPMENT

## ARCOSA AGG - FRONT AXLE



**Sample No:** VCP06068779  
**Oil Type:** GEAR OIL SAE 90  
**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP06068779	---	---	---
Sample Date	02 Jan 2024	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

**SCOTT EQUIPMENT COMPANY LLC - Baton Rouge**  
 10160 AIRLINE HWY  
 BATON ROUGE, LA  
 US 70816  
 Contact: BRENT CALDWELL  
 bcaldwell@scottcompanies.com  
 T: (225)293-3683  
 F: (225)292-9658



### OIL CONDITION

Visc @ 40°C	cSt	█ 109	---	---	---
-------------	-----	-------	-----	-----	-----



### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 5	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 0	---	---	---



### WEAR METALS

Iron	ppm	█ 101	---	---	---
Copper	ppm	█ 15	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 1	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 2	---	---	---
Molybdenum	ppm	█ 3	---	---	---
Nickel	ppm	█ 2	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 4	---	---	---
Vanadium	ppm	<1	---	---	---



### ADDITIVES

Calcium	ppm	█ 285	---	---	---
Magnesium	ppm	█ 2	---	---	---
Zinc	ppm	█ 127	---	---	---
Phosphorus	ppm	█ 1010	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 190	---	---	---

### Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 90. Please confirm. Please specify the component make and model with your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO6242  
**Unique No:** 10845456  
**Signed:** Wes Davis  
**Report Date:** 24 Jan 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

