



# CONSTRUCTION EQUIPMENT

660415 VOLVO A30G 752984 - REAR AXLE



**Sample No:** VCP437632  
**Oil Type:** VOLVO PREMIUM GEAR OIL 85W-140 GL-5  
**Job No:** 660415



## SAMPLE INFORMATION

Sample Number	VCP437632	---	---	---
Sample Date	18 Jan 2024	---	---	---
Machine Hours	1183	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	ATTENTION	---	---	---

**WLW CONSTRUCTION**  
 PO BOX 377  
 MT DORA, FL  
 US 32756-0377  
 Contact: ELAINE STULTZ  
 elaine@wlwconstruction.com  
 T: (352)383-7305  
 F:

## OIL CONDITION

Visc @ 40°C	cSt	▲ 87.0	---	---	---
-------------	-----	--------	-----	-----	-----

## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 6	---	---	---
Sodium	ppm	■ 2	---	---	---
Potassium	ppm	■ 6	---	---	---

## WEAR METALS

Iron	ppm	■ 370	---	---	---
Copper	ppm	■ 15	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 1	---	---	---
Aluminum	ppm	■ 0	---	---	---
Chromium	ppm	■ 7	---	---	---
Molybdenum	ppm	■ 13	---	---	---
Nickel	ppm	■ 3	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 11	---	---	---
Vanadium	ppm	<1	---	---	---

## ADDITIVES

Calcium	ppm	▲ 1091	---	---	---
Magnesium	ppm	■ 3	---	---	---
Zinc	ppm	▲ 427	---	---	---
Phosphorus	ppm	▲ 1345	---	---	---
Barium	ppm	■ 4	---	---	---
Boron	ppm	■ 240	---	---	---

**Diagnosis**  
 The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. This plus the additive levels indicates the addition of a different brand, or type of oil. Confirm oil type.

**Depot:** WLWMOU  
**Unique No:** 10845485  
**Signed:** Sean Felton  
**Report Date:** 25 Jan 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

