



# CONSTRUCTION EQUIPMENT

## X59122 TADANO GR350 562344 - TRANSMISSION (AUTO)



**Sample No:** VCP429328  
**Oil Type:** DEXRON III  
**Job No:** X59122



### SAMPLE INFORMATION

Sample Number	VCP429328	---	---	---
Sample Date	18 Jan 2024	---	---	---
Machine Hours	1959	---	---	---
Oil Hours	1959	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

**SCOTT EQUIPMENT COMPANY LLC - Saint Rose**  
 PO BOX 997  
 SAINT ROSE, LA  
 US 70087  
 Contact: DANA FOSHEE  
 dfoshee@scottcompanies.com  
 T: (504)461-0961  
 F: (504)461-0970



### OIL CONDITION

Visc @ 40°C	cSt	█ 29.1	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 3	---	---	---
Sodium	ppm	█ <1	---	---	---
Potassium	ppm	█ 0	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



### WEAR METALS

Iron	ppm	█ 0	---	---	---
Copper	ppm	█ <1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 0	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	█ 68	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 0	---	---	---
Phosphorus	ppm	█ 195	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 100	---	---	---

**Depot:** SCOSAI  
**Unique No:** 10845523  
**Signed:** Sean Felton  
**Report Date:** 25 Jan 2024



# CONSTRUCTION EQUIPMENT




## GRAPHS

### Iron (ppm)




### Lead (ppm)



### Aluminum (ppm)




### Chromium (ppm)



### Copper (ppm)



### Silicon (ppm)



### Viscosity @ 40°C



### Additives

