CONSTRUCTION EQUIPMENT 635043 US TENT RENT AVANT M528 1044032115 - HYDRAULIC

Sample No:VCP432021Oil Type:VOLVO SUPER HYDRAULIC OIL 46

VOLVO

Job No: 635043 US TENT RENT

SAMPLE INFORMATION Sample Number VCP432021 VCP411077 Sample Date 06 Dec 2023 20 Apr 2023 Machine Hours 823 644 Oil Hours 400 644 Oil Changed Changed Changed ABNORMAL SEVERE Sample Status **OIL CONDITION** 43.0 Visc @ 40°C cSt 44.5 Acid Number (AN) mg KOH/g 0.35 0.32 CONTAMINATION

Water	%	NEG	NEG	
Particles >4µm		<u> </u>	84431	
Particles >6µm		689	3 597	
Particles >14µm		10	7	
ISO 4406:1999 (c) 22/17/10		22/17/10	24/19/10	
Silicon	ppm	6	7	
Sodium	ppm	2	5	
Potassium	ppm	2	2	

WEAR METAL

Iron	ppm	9	17	
Copper	ppm	□ <1	2	
Lead	ppm	□<1	1	
Tin	ppm		<1	
Aluminum	ppm	□<1	0	
Chromium	ppm	0	 <1	
Molybdenum	ppm	3	<1	
Nickel	ppm	0	 <1	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	□<1	 <1	
Vanadium	ppm	0	0	

VOLVO

Calcium	ppm	143	57				
Magnesium	ppm	1 4	4				
Zinc	ppm	403	447				
Phosphorus	ppm	330	342				
Barium	ppm	0	0				
Boron	ppm	6	0				



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC

8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: JOHN FARDELLA john.fardella@altg.com T: (813)630-0077 F: (813)630-2233

Diagnosis

The filter change at the time of sampling has been noted. We recommend an early resample to monitor this condition.All component wear rates are normal. There is a moderate amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

 Depot:
 VOLVO0093

 Unique No:
 10846182

 Signed:
 Wes Davis


 Report Date:
 25 Jan 2024

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO0093 [WUSCAR] 06069505 (Generated: 01/25/2024 18:41:04) Rev: 1

Contact/Location: JOHN FARDELLA - VOLVO0093