CONSTRUCTION EQUIPMENT 634846 RYAN GOLF VOLVO A45G 352377 - HYDRAULIC SYSTEM

Sample No: VCP441467 Oil Type: VOLVO SUPER

VOLVO

VOLVO SUPER HYDRAULIC OIL 46

634846 RYAN GOLF

Job No:

SAMPLE INFORMATION Sample Number VCP441467 VCP345895 Sample Date 05 Dec 2023 04 Feb 2022 Machine Hours 4150 1992 Oil Hours 4150 0 Oil Changed Changed Not Changd NORMAL ABNORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 45.9 42.0 Acid Number (AN) mg KOH/g 0.34 0.30 FONTAMINATION

	INATION			
Water	%	NEG	NEG	
Particles >4µm		24844	121669	
Particles >6µm		1448	<u> </u>	
Particles >14µm		52	▲ 821	
ISO 4406:1999 (c)		22/18/13	24/22/17	
Silicon	ppm	8	5	
Sodium	ppm	2	1	
Potassium	ppm	□ <1	0	

WEAR METALS

Iron	ppm	8	7	
Copper	ppm	2	2	
Lead	ppm	2	2	
Tin	ppm	□<1	1	
Aluminum	ppm	3	<1	
Chromium	ppm	0	 <1	
Molybdenum	ppm	0	0	
Nickel	ppm	0	0	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	□<1	0	
Vanadium	ppm	0	0	

VOLVO

ADDITIVES								
Calcium	ppm	60	50					
Magnesium	ppm	2	0					
Zinc	ppm	386	453					
Phosphorus	ppm	310	398					
Barium	ppm	0	0					
Boron	ppm		<1					



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC

8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: JOHN FARDELLA john.fardella@altg.com T: (813)630-0077 F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

 Depot:
 VOLVO0093

 Unique No:
 10846183

 Signed:
 Wes Davis


 Report Date:
 25 Jan 2024

CONSTRUCTION EQUIPMENT



🥖 GRAPHS

VOLVO



Report Id: VOLVO0093 [WUSCAR] 06069506 (Generated: 01/25/2024 18:40:56) Rev: 1

Contact/Location: JOHN FARDELLA - VOLVO0093