

## **CONSTRUCTION EQUIPMENT**

634846 RYAN GOLF VOLVO A45G 352377 - DROP BOX



Sample No: VCP426180

Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5

**Job No:** 634846 RYAN GOLF

SAMPLE	INFORMATION			
Sample Number		VCP426180	VCP345860	 
Sample Date		05 Dec 2023	05 Feb 2022	 
Machine Hours		4150	1992	 
Oil Hours		4150	0 Not Changd	 
Oil Changed		Changed		
Sample Status		ABNORMAL	ABNORMAL	 
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>▲</b> 56.3	<b>□</b> 57.2	 
VOLVO	IINA TION			
CONTAM	IINATIUN			
Water	%	NEG	NEG	 
Silicon	ppm	<u></u> ▲ 61	<b>△</b> 53	 
Sodium	ppm	<b>■3</b>	<b>4</b>	 
Potassium	ppm	<b>■</b> 9	<b>3</b>	 
WEAR M	ETAL C			
Iron	ppm	<u>▲</u> 862	<b>441</b>	 
Copper	ppm	■20	<b>1</b> 2	 
Lead	ppm	<b></b>	<b>-</b> <1	 
Tin	ppm	■0	<b>-</b> <1	 
Aluminum	ppm	■1	■5	 
Chromium	ppm	<b>■7</b>	<b>5</b>	 
Molybdenum	ppm	■25	10	 
Nickel	ppm	<b>6</b>	<b>3</b>	 
Titanium	ppm	<1	0	 
Silver	ppm	0	0	 
Manganese	ppm	<b>1</b> 3	7	 
Vanadium	ppm	0	0	 
ADDITIV	ES			
	_		48	
Calcium	ppm	<b>72</b>		 
Magnesium	ppm	<b>9</b>	4	 
Zinc	ppm	<b>131</b>	93	 
Phosphorus	ppm	<b>■</b> 1579	1919	 
Barium	ppm	<b>0</b>	0	 
Boron	ppm	<b>71</b>	122	 



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233

## Diagnosis

The oil change at the time of sampling has been noted. No corrective action is recommended at this time. Resample at the next service interval to monitor. Gear wear is indicated. All other component wear rates are normal. Elemental level of silicon (Si) above normal. The oil viscosity is lower than normal. Confirm oil type.

Depot:VOLVO0093Unique No:10846424Signed:Don BaldridgeReport Date:26 Jan 2024



## **CONSTRUCTION EQUIPMENT**





