



# CONSTRUCTION EQUIPMENT

## 24843 VOLVO A60 350319 - FRONT AXLE



**Sample No:** VCP441247  
**Oil Type:** VOLVO SUPER GEAR OIL 75W-80-GO102  
**Job No:** 24843



### SAMPLE INFORMATION

Sample Number	VCP441247	---	---	---
Sample Date	19 Jan 2024	---	---	---
Machine Hours	526	---	---	---
Oil Hours	500	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---

218 - ASCENDUM MACHINERY INC - N. CHARLESTON  
 7235 CROSS COUNTRY RD.  
 NORTH CHARLESTON, SC  
 US 29418  
 Contact: MATT MITCHAM  
 matt.mitcham@ascendummachinery.com  
 T:  
 F: (843)414-1129



### OIL CONDITION

Visc @ 40°C	cSt	■ 52.6	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	■ 2	---	---	---
Sodium	ppm	■ 0	---	---	---
Potassium	ppm	■ 3	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



### WEAR METALS

Iron	ppm	■ 86	---	---	---
Copper	ppm	■ 2	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ <1	---	---	---
Aluminum	ppm	■ 1	---	---	---
Chromium	ppm	■ 2	---	---	---
Molybdenum	ppm	■ 2	---	---	---
Nickel	ppm	■ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 5	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	■ 46	---	---	---
Magnesium	ppm	■ 1	---	---	---
Zinc	ppm	■ 20	---	---	---
Phosphorus	ppm	■ 2093	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 314	---	---	---

**Depot:** VOLVO3387  
**Unique No:** 10846447  
**Signed:** Don Baldrige  
**Report Date:** 26 Jan 2024



# CONSTRUCTION EQUIPMENT



## GRAPHS

