



CONSTRUCTION EQUIPMENT

616970 FRITZ VOLVO L70H 623207 - COOLANT



Sample No: VCP440451
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: 616970 FRITZ



SAMPLE INFORMATION

| | | | | |
|---------------|-------------|-----|-----|-----|
| Sample Number | VCP440451 | --- | --- | --- |
| Sample Date | 15 Jan 2024 | --- | --- | --- |
| Machine Hours | 6390 | --- | --- | --- |
| Sample Status | NORMAL | --- | --- | --- |

ALTA EQUIPMENT COMPANY - METRO WEST
56195 PONTIAC TRAIL
NEW HUDSON, MI
US 48165
Contact: PAUL CONZ
paul.conz@altg.com
T: (313)348-8861
F: (248)356-2029



COOLANT CONDITION

| | | | | | |
|--------------------|------------|--------|-----|-----|-----|
| pH | Scale 0-14 | ■ 8.02 | --- | --- | --- |
| Reserve Alkalinity | Scale 0-20 | --- | --- | --- | --- |
| Nitrites | ppm | ■ NT | --- | --- | --- |
| Percentage Glycol | % | ■ 58.9 | --- | --- | --- |
| Freezing Point | °C | ■ -54 | --- | --- | --- |

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

| | | | | |
|--------------------|--------|-----|-----|-----|
| Coolant Appearance | normal | --- | --- | --- |
| Coolant Color | Yllow | --- | --- | --- |

Depot: VOLVO2990
Unique No: 10846490
Signed: Jonathan Hester
Report Date: 26 Jan 2024




CONSTRUCTION EQUIPMENT




VOLVO GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

