



CONSTRUCTION EQUIPMENT

VOLVO L110H 625924 - COOLANT



Sample No: VCP439476
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No:



SAMPLE INFORMATION

Sample Number	VCP439476	---	---	---
Sample Date	19 Jan 2024	---	---	---
Machine Hours	2355	---	---	---
Sample Status	NORMAL	---	---	---

CITY CARTING

221 OLD GATE LN
MILFORD, CT
US 06460
Contact: TAVINS BANKS
tavins@citycart.net
T: (203)223-3885
F:



COOLANT CONDITION

pH	Scale 0-14	■ 7.62	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 52.4	---	---	---
Freezing Point	°C	■ -40	---	---	---

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Red	---	---	---

Depot: CITMILCON
Unique No: 10846856
Signed: Jonathan Hester
Report Date: 26 Jan 2024




CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

