

CONSTRUCTION EQUIPMENT VOLVO L70H 625066 - DIESEL ENGINE

OIL SAE 40



Sample No: VCP0007774

Oil Type:	DIESEL	ENGINE
-----------	--------	--------

Job No:

	NFORMATION				
Sample Number		VCP0007774		·	
Sample Date		22 Jan 2024			
Machine Hours		1037			
Dil Hours		1037			
Dil Changed		N/A			
Sample Status		NORMAL			
OIL CONDI	TION				
	-	·	-		
/isc @ 100°C	cSt	12.9			
Base Number (BN)		8.6			
Dxidation (PA)	%	75			
VOLVO					
Contamii	NATION				
Water	%	NEG			
Soot %	%	0.5			
Nitration (PA)	%	73			
Sulfation (PA)	%	60			
Glycol	%	NEG			
uel	%	<1.0			
Silicon	ppm	22			
Sodium	ppm	 <1			
Potassium	ppm	0			
WEAR ME	ΤΛΙς				
	-			<u>.</u>	
ron	ppm	■ 31			
Copper	ppm	8			
_ead	ppm	2			
lin .	ppm	3			
Aluminum	ppm	1 5			
Chromium	ppm	4			
Molybdenum	ppm	5 1			
Nickel	ppm	□ <1			
litanium	ppm	0			
Viluer.	ppm	0			
Silver	10.10.100				
Manganese	ppm	■4			
	ppm ppm	0			
Manganese /anadium	ppm				
Manganese	ppm				
Manganese /anadium ADDITIVE	ppm S	0			
Manganese /anadium ADDITIVE Calcium	ppm S ppm	0			
Manganese /anadium ADDITIVE Calcium Magnesium	ppm S ppm ppm	0			
Manganese Vanadium ADDITIVE Calcium Magnesium Zinc	ppm S ppm ppm ppm	0 1476 542 1139			
Manganese /anadium ADDITIVE Calcium Magnesium	ppm S ppm ppm	0 1476 542			



ALTA EQUIPMENT COMPANY

3750 PHILIPS HWY IACKSONVILLE, FL JS 32256 Contact: SHAWN NORTHCRAFT shawn.northcraft@altg.com T: (904)737-6000 F: (904)737-1260

Diagnosis

Resample at the next service interval to monitor.Metal levels are typical for a new component breaking in. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

 Depot:
 VOLVO0092

 Unique No:
 10846885

 Signed:
 Don Baldridge

 Report Date:
 26 Jan 2024

Submitted By: TECHNICIAN ACCOUNT


Report Id: VOLVO0092 [WUSCAR] 06070208 (Generated: 01/26/2024 15:48:31) Rev: 1

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO0092 [WUSCAR] 06070208 (Generated: 01/26/2024 15:48:34) Rev: 1

Submitted By: TECHNICIAN ACCOUNT