

CONSTRUCTION EQUIPMENT VOLVO L70H 625066 - HYDRAULIC SYSTEM



Sample No: VCP0007772

Oil Type: AW HYDRAULIC OIL ISO 46

Job No:

VOLVO					
SAMPLE	INFORMATION				
Sample Number	-	VCP0007772			
Sample Date		22 Jan 2024			
Machine Hours		1037			
Oil Hours		1037			
Oil Changed		N/A			
Sample Status		NORMAL			
VOLVO	ITION				
OIL COND	IIIUN				
Visc @ 40°C	cSt	44.0			
Acid Number (AN)	mg KOH/g	0.49			
CONTAMINATION					
	-			<u>.</u>	
Water	%	NEG			
Particles >4µm		2410			
Particles >6µm		442			
Particles >14µm		22			
ISO 4406:1999 (c)		18/16/12			
Silicon	ppm	■ 0			
Sodium	ppm	1			
Potassium	ppm	■ 0			
VOLVO					
WEAR ME	TALS				
Iron		0			
Copper	ppm	0			
Lead		■0			
Tin	ppm	■0			
Aluminum	ppm	■0			
Chromium	ppm	0			
	ppm				
Molybdenum Nickel	ppm	0			
Titanium	ppm	0			
Silver	ppm	0			
	ppm				
Manganese	ppm	0			
Vanadium	ppm	<1			
VOLVO					
ADDITIVE	2				
Calcium	ppm	■ 77			
Magnesium	ppm	■0			
Zinc	ppm	458			
Phosphorus	ppm	384			
Barium	ppm	■0			
Boron	ppm	■0			
טוטוו	ppiii				



ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY JACKSONVILLE, FL US 32256

Contact: TECHNICIAN ACCOUNT catherine.anastasio@wearcheck.com

F: (904)737-1260

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AW HYDRAULIC OIL ISO 46. Please confirm.

All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot:VOLVO0092Unique No:10847072Signed:Wes DavisReport Date:26 Jan 2024

Submitted By: TECHNICIAN ACCOUNT



CONSTRUCTION EQUIPMENT





GRAPHS

