

CONSTRUCTION EQUIPMENT VOLVO L70H 625052 - HYDRAULIC SYSTEM



Sample No: VCP0007777

Oil Type: AW HYDRAULIC OIL ISO 46

Job No:

VOLVO	NEODMATION				
	NFORMATION				
Sample Number		VCP0007777			
Sample Date		22 Jan 2024			
Machine Hours		566			
Oil Hours		566			
Oil Changed		N/A			
Sample Status		NORMAL			
OIL CONDI	TION				
				<u>.</u>	
Visc @ 40°C	cSt	43.9			
Acid Number (AN)	mg KOH/g	0.52			
VOLVO					
CONTAMINATION					
Water	%	NEG			
Particles >4µm	/0	2420			
Particles >6µm		■449			
Particles > 14µm		21			
ISO 4406:1999 (c)		18/16/12			
Silicon	10.10.100				
Sodium	ppm	0			
	ppm	■ <1			
Potassium	ppm	0			
VOLVO					
WEAR ME	TALS				
Iron	ppm	0			
Copper	ppm	■0			
Lead	ppm	■0			
Tin	ppm	■0			
Aluminum	ppm	■0			
Chromium	ppm	■0			
Molybdenum	ppm	■0			
Nickel	ppm	■0			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	■0			
Vanadium	ppm	<1			
VOLVO	_				
ADDITIVE	7				
Calcium	ppm	77			
Magnesium	ppm	■ 0			
Zinc	ppm	458			
Phosphorus	ppm	■389			
Barium	ppm	0			
Boron	ppm	■ 0			



ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY JACKSONVILLE, FL US 32256

Contact: TECHNICIAN ACCOUNT catherine.anastasio@wearcheck.com

F: (904)737-1260

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AW HYDRAULIC OIL ISO 46. Please confirm.

All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot:VOLVO0092Unique No:10847073Signed:Wes DavisReport Date:26 Jan 2024

Submitted By: TECHNICIAN ACCOUNT



CONSTRUCTION EQUIPMENT





GRAPHS

