
## CONSTRUCTION EQUIPMENT SW-28852-2 FX CONSTR VOLVO L120H 633201 - FRONT AXLE



VOLVO

•	
Oil Type:	VOLVO SUPER WET BRAKE TRANSAXLE OIL WB102
Job No:	SW-28852-2 FX CONSTR

## SAMPLE INFORMATION VCP436519 Sample Number Sample Date 18 Jan 2024 **ARNOLD MACHINERY COMPANY** Machine Hours 958 2975 WEST 2100 SOUTH Oil Hours 958 SALT LAKE CITY, UT US 84119 Oil Changed Changed NORMAL Contact: TONY PAYAN Sample Status tpayan@arnoldmachinery.com T: (801)972-4000 **OIL CONDITION** F: (801)975-9434 Visc @ 40°C cSt 40.7 Diagnosis CONTAMINATION Resample at the next service interval Water % NEG to monitor.All component wear rates Silicon are normal. There is no indication of 31 ppm any contamination in the oil. The Sodium 9 🔲 ppm condition of the oil is acceptable for Potassium ppm 2 the time in service. WEAR METALS 235 Iron ppm Copper ppm 3 Lead ppm **||** <1 Tin ppm 0 🔲 Aluminum 2 ppm Chromium 6 🔲 ppm Molybdenum ppm 10 Nickel 1 ppm Titanium ppm <1 Silver 0 ppm Manganese ppm 11 Vanadium ppm 0 101 **ADDITIVES** Calcium 3781 ppm Magnesium 15 ppm Zinc ppm 1616 Phosphorus 1310 ppm



Depot:

Signed:

Unique No:

0 🔲

133

ppm

ppm

Barium

Boron

VOLV08770

10847425


Wes Davis

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Report Id: VOLVO8770 [WUSCAR] 06070748 (Generated: 01/26/2024 10:07:55) Rev: 1

Contact/Location: TONY PAYAN - VOLVO8770