



CONSTRUCTION EQUIPMENT

VOLVO A25G 752029 - TRANSMISSION (AUTO)



Sample No: VCP0007768

Oil Type: DEXRON III

Job No:



SAMPLE INFORMATION

Sample Number	VCP0007768	VCP0006168	VCP317166	VCP304126
Sample Date	22 Jan 2024	07 Dec 2022	27 Aug 2021	20 Apr 2021
Machine Hours	4074	2283	2283	1567
Oil Hours	4074	2283	2283	1567
Oil Changed	N/A	N/A	Changed	Not Changd
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

ALTA EQUIPMENT COMPANY

8750 PHILIPS HWY
JACKSONVILLE, FL
US 32256

Contact: SHAWN NORTHCRAFT
shawn.northcraft@altg.com
T: (904)737-6000
F: (904)737-1260



OIL CONDITION

Visc @ 40°C	cSt	28.8	27.8	29.3	28.8
-------------	-----	-------------	------	------	------



CONTAMINATION

Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	5	6	13	0
Sodium	ppm	3	5	8	0
Potassium	ppm	<1	3	10	0



WEAR METALS

Iron	ppm	16	26	37	1
Copper	ppm	22	28	65	0
Lead	ppm	0	1	0	0
Tin	ppm	4	8	9	0
Aluminum	ppm	11	22	42	0
Chromium	ppm	0	<1	<1	0
Molybdenum	ppm	0	<1	0	<1
Nickel	ppm	3	4	10	0
Titanium	ppm	0	0	0	0
Silver	ppm	0	0	0	0
Manganese	ppm	1	1	3	0
Vanadium	ppm	0	0	0	0



ADDITIVES

Calcium	ppm	69	86	154	76
Magnesium	ppm	0	2	0	<1
Zinc	ppm	2	0	5	0
Phosphorus	ppm	187	205	252	198
Barium	ppm	0	0	0	0
Boron	ppm	85	77	77	101

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DEXRON III. Please confirm. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: VOLVO0092
Unique No: 10847474
Signed: Wes Davis
Report Date: 26 Jan 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

