



CONSTRUCTION EQUIPMENT

VOLVO A60H 340039 - FRONT RIGHT FINAL DRIVE



Sample No: VCP441432
Oil Type: GEAR OIL SAE 80W140
Job No:



SAMPLE INFORMATION

Sample Number	VCP441432	VCP428986	VCP412654	VCP387918
Sample Date	18 Jan 2024	27 Sep 2023	20 Jun 2023	29 Nov 2022
Machine Hours	8521	8052	7542	7061
Oil Hours	0	0	0	0
Oil Changed	Not Changd	Changed	Not Changd	Not Changd
Sample Status	NORMAL	NORMAL	NORMAL	NORMAL

SAIIA CONSTRUCTION LLC
 4400 LEWISBURG RD
 BIRMINGHAM, AL
 US 35207
 Contact: STEPHANI BRITTON
 sbritton@saiia.com;doug.bogart@wearcheck.com
 T: (205)943-2268
 F: (205)943-2269



OIL CONDITION

Visc @ 40°C	cSt	282	275	276	273
-------------	-----	------------	-----	-----	-----



CONTAMINATION

Water	%	NEG	NEG	NEG	NEG
Silicon	ppm	3	3	3	2
Sodium	ppm	2	<1	<1	0
Potassium	ppm	1	1	0	0

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	10	24	34	20
Copper	ppm	0	<1	0	<1
Lead	ppm	0	0	0	0
Tin	ppm	<1	<1	0	0
Aluminum	ppm	0	0	0	<1
Chromium	ppm	0	<1	<1	<1
Molybdenum	ppm	6	2	3	3
Nickel	ppm	<1	0	<1	0
Titanium	ppm	0	0	0	0
Silver	ppm	0	0	0	0
Manganese	ppm	<1	<1	<1	<1
Vanadium	ppm	0	0	0	0



ADDITIVES

Calcium	ppm	99	67	80	78
Magnesium	ppm	35	14	19	16
Zinc	ppm	95	24	42	47
Phosphorus	ppm	773	912	1022	937
Barium	ppm	<1	0	0	0
Boron	ppm	135	149	188	163

Depot: SAIBIR
Unique No: 10848652
Signed: Sean Felton
Report Date: 30 Jan 2024



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

