CONSTRUCTION EQUIPMENT VOLVO EC250EL 310704 - LEFT FINAL DRIVE X11086





Machine Hours

Oil Hours

Oil Changed

Sample Status

Visc @ 40°C

Water

Silicon

Sodium

Potassium

OIL CONDITION

CONTAMINATION

cSt

%

ppm

ppm

ppm

VOLVO

SAMPLE INFORMATION VCP431866 Sample Number Sample Date 24 Jan 2024

6009

Not Changd

ABNORMAL

223


0.227


26

1 🔲

4

0







810 WEST PINE STREET WARREN, AR US 71671 Contact: SERVICE MANAGER

T: (870)226-2611 F:

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. Please note that this is a corrected copy for data entry update for hours on unit.All component wear rates are normal. There is a light concentration of water present in the oil. The condition of the oil is acceptable for the time in service.

WEAR METALS					
Iron	ppm	193			
Copper	ppm				
Lead	ppm	0			
Tin	ppm	0			
Aluminum	ppm	7			
Chromium	ppm	5			
Molybdenum	ppm	□<1			
Nickel	ppm				
Titanium	ppm	<1			
Silver	ppm	0			
Manganese	ppm	1			
Vanadium	ppm	0			


ADDITIVES Calcium 8 ppm Magnesium ppm 2 🔲 Zinc ppm 0 Phosphorus 254 ppm Barium ppm 0 🔲 14 Boron ppm

Depot: POTWAR Unique No: 10849055 Signed: Doug Bogart Report Date: 30 Jan 2024

CONSTRUCTION EQUIPMENT



VOLVO



Report Id: POTWAR [WUSCAR] 06072378 (Generated: 01/30/2024 23:41:29) Rev: 2

Contact/Location: SERVICE MANAGER - POTWAR