

CONSTRUCTION EQUIPMENT G60837 FBS TIRE VOLVO L120F 25666 - REAR AXLE



Sample No: VCE63596

Oil Type: VOLVO SUPER WET BRAKE TRANSAXLE OIL WB102

Report Id: VOLVO0049 [WUSCAR] 06074162 (Generated: 01/31/2024 04:36:29) Rev: 1

Job No: G60837 FBS TIRE

CAMPI F	INFORMATION			
Sample Number		VCE63596	 	
Sample Date		24 Jan 2024	 	
Machine Hours		26539	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		NORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	42.5	 	
VI3C @ 40 C	CSt	TL. 3		
VOLVO				
CONTAN	MINATION			
Water	%	NEG	 	
Silicon	ppm	17	 	
Sodium	ppm	■<1	 	
Potassium	ppm	3	 	
VOLVO	AFTALC			
WEAR N	IETALS			
Iron	ppm	76	 	
Copper	ppm	■<1	 	
Lead	ppm	■<1	 	
Tin	ppm	■<1	 	
Aluminum	ppm	2	 	
Chromium	ppm	■<1	 	
Molybdenum	ppm	■<1	 	
Nickel	ppm	-<1	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm		 	
Vanadium	ppm	0	 	
	•			
VOLVO	IEC			
ADDITIV	(2)			
Calcium	ppm	4038	 	
Magnesium	ppm	14	 	
Zinc	ppm	1651	 	
Phosphorus	ppm	1197	 	
Barium	ppm	0	 	
Boron	ppm	144	 	



CHADWICK-BAROSS INC

ROUTE106 237 SHEEP DAVIS ROAD CONCORD, NH US 03301 Contact: DOMINIC RUGGIERO ruggiero@chadwick-baross.com T: F: (603)224-3001

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO0049Unique No:10856253Signed:Wes DavisReport Date:31 Jan 2024



CONSTRUCTION EQUIPMENT





