



CONSTRUCTION EQUIPMENT

SWA407546 THREE LAKE VOLVO L60H 623021 - REAR AXLE



Sample No: VCP449122
Oil Type: VOLVO WB 102
Job No: SWA407546 THREE LAKE



SAMPLE INFORMATION

Sample Number	VCP449122	---	---	---
Sample Date	18 Jan 2024	---	---	---
Machine Hours	2521	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT COMPANY

5210 REESE ROAD
DAVIE, FL
US 33314

Contact: N. FACEY
nfacey@altaequipfl.com
T: (954)581-4744
F: (954)583-0318



OIL CONDITION

Visc @ 40°C	cSt	█ 40.7	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 19	---	---	---
Sodium	ppm	█ 9	---	---	---
Potassium	ppm	█ <1	---	---	---



WEAR METALS

Iron	ppm	█ 141	---	---	---
Copper	ppm	█ 28	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 4	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ 5	---	---	---
Molybdenum	ppm	█ 2	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 7	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 3826	---	---	---
Magnesium	ppm	█ 6	---	---	---
Zinc	ppm	█ 1598	---	---	---
Phosphorus	ppm	█ 1267	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 120	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0095
Unique No: 10857288
Signed: Wes Davis
Report Date: 01 Feb 2024



CONSTRUCTION EQUIPMENT



GRAPHS

