## CONSTRUCTION EQUIPMENT 661670 ALTA RENTS VOLVO EC380 315586 - HYDRAULICSYSTE

Sample No: VCP436813 Oil Type: VOLVO SUPER

VOLVO

Job No:

VOLVO SUPER HYDRAULIC OIL 46 661670 ALTA RENTS

	-
NOT	100

## **SAMPLE INFORMATION** VCP436813 Sample Number Sample Date 26 Jan 2024 Machine Hours 523 Oil Hours 0 Oil Changed Not Changd NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 41.8 Acid Number (AN) mg KOH/g 0.49 CONTAMINATION

Water	%	NEG	 	
Particles >4µm		21296	 	
Particles >6µm		5022	 	
Particles >14µm		<b>165</b>	 	
ISO 4406:1999 (c)		22/20/15	 	
Silicon	ppm	3	 	
Sodium	ppm	□ <1	 	
Potassium	ppm	□<1	 	

WEAR METAL

Iron	ppm	<b>1</b>	 	
Copper	ppm	<b>15</b>	 	
Lead	ppm	0	 	
Tin	ppm	<b></b> <1	 	
Aluminum	ppm	<b></b> <1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	<b></b> <1	 	
Vanadium	ppm	<1	 	

VOLVO

Calcium	ppm	79			
Magnesium	ppm	0			
Zinc	ppm	485			
Phosphorus	ppm	<b>403</b>			
Barium	ppm	0			
Boron	ppm	0			



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC

9601 BOGGY CREEK RD ORLANDO, FL US 32824 Contact: Robert LaPlante robert.laplante@altg.com T: (407)508-9736 F: (407)659-8720

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

 Depot:
 VOLVO0096

 Unique No:
 10857750

 Signed:
 Wes Davis


 Report Date:
 01 Feb 2024

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Report Id: VOLVO0096 [WUSCAR] 06075659 (Generated: 02/01/2024 10:33:46) Rev: 1

Contact/Location: Robert LaPlante - VOLVO0096