

CONSTRUCTION EQUIPMENT VOLVO L90H 05625448 - FRONT AXLE



Sample No: VCP438656
Oil Type: VOLVO WB 102

Job No:

SAMPLI	E INFORMATIO	N		
Sample Number		VCP438656	VCP411570	
Sample Date		23 Jan 2024	10 Oct 2023	
Machine Hours		0	5552	
Oil Hours		0	0	
Oil Changed		Changed	Changed	
Sample Status		ABNORMAL	NORMAL	
VOLVO	IDITION			
OIL CON	אטווועו			
Visc @ 40°C	cSt	43.3	42.8	
VOLVO				
CONTAR	MINATION			
Water	%	NEG	NEG	
Silicon				
Sodium	ppm	□14 □0	□15 □2	
Potassium	ppm	1	0	
Potassium	ppm		0	
VOLVO				
WEAR N	METALS			
Iron	ppm	14	□ 31	
Copper	ppm	<1	0	
Lead	ppm	0	0	
Tin	ppm	O	0	
Aluminum	ppm	2	 <1	
Chromium	ppm	-<1	 <1	
Molybdenum	ppm		0	
Nickel	ppm	■ 0	0	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	■ <1	2	
Vanadium	ppm	0	0	
ADDITIV	VES			
Calcium	ppm	3922	□3887	
Magnesium	ррт	21	19	
Zinc	ppm	■ 1610	□ 19 □ 1576	
Phosphorus	ppm	1286	1279	
Barium	ppm	■ <1	1279 <1	
Boron		135	133	
ווטוטוו	ppm	<u> </u>	<u> </u>	



CITY CARTING

221 OLD GATE LN MILFORD, CT US 06460 Contact: TAVINS BANKS tavins@citycart.net T: (203)223-3885 F:

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. Moderate concentration of visible dirt/debris present in the oil. The condition of the oil is acceptable for the time in service.

Depot:CITMILCONUnique No:10858209Signed:Jonathan HesterReport Date:02 Feb 2024



CONSTRUCTION EQUIPMENT





GRAPHS

