

CONSTRUCTION EQUIPMENT 5224HR NEW ENT VOLVO EC290CLR 111059 - COOLANT

Sample No: VCP371058
Oil Type: {unknown}

Job No: 5224HR NEW ENT

SAMPLE II	NFORMATION				
Sample Number	-	VCP371058			
Sample Date		25 Jan 2024			
Machine Hours		8193			
Sample Status		NORMAL			
COOLANT CONDITION					
рН	Scale 0-14	■8.68			
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	412			
Percentage Glycol	%	50.8			
Freezing Point	°C	□ -35			
CONTAMIN	NATION				
Coolant Appearance		normal			
Coolant Color		Blue			



HIGHWAY EQUIPMENT & SUPPLY CO MAIN PO BOX 1957 HARRISBURG, PA US 17105

Contact: CHAD HERRON

T: 7(175)643-3031 F: (717)564-3568

Diagnosis

The fluid is suitable for further service. No evidence of fuel present in the coolant. There is no indication of any contamination in the coolant. Glycol and nitrite levels are acceptable. The pH level of this fluid is within the acceptable limits.

Depot:VOLVO0025Unique No:10858370Signed:Jonathan HesterReport Date:05 Feb 2024



CONSTRUCTION EQUIPMENT





GRAPHS

