



# CONSTRUCTION EQUIPMENT

## VOLVO L90H 05625448 - COOLANT



**Sample No:** VCP437123  
**Oil Type:** VOLVO COOLANT (GREEN)  
**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP437123	---	---	---
Sample Date	23 Jan 2024	---	---	---
Machine Hours	0	---	---	---
Sample Status	NORMAL	---	---	---

**CITY CARTING**  
 221 OLD GATE LN  
 MILFORD, CT  
 US 06460  
 Contact: JOHN LINARES  
 jlinares@win-waste.com  
 T:  
 F:



### COOLANT CONDITION

pH	Scale 0-14	■ 7.61	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 51.0	---	---	---
Freezing Point	°C	■ -38	---	---	---

### Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



### CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

**Depot:** CITMILCON  
**Unique No:** 10858372  
**Signed:** Jonathan Hester  
**Report Date:** 05 Feb 2024



# CONSTRUCTION EQUIPMENT




## GRAPHS


### Iron/Tin/Silver




### Reserve Alkalinity




### Copper/Aluminum/Lead



### Freeze Point



### pH



### Nitrites

