



CONSTRUCTION EQUIPMENT

11976 VOLVO L120F 66750 - COOLANT



Sample No: VCP444087
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: 11976



SAMPLE INFORMATION

Sample Number	VCP444087	---	---	---
Sample Date	24 Jan 2024	---	---	---
Machine Hours	19000	---	---	---
Sample Status	NORMAL	---	---	---



COOLANT CONDITION

pH	Scale 0-14	■ 7.64	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 50.9	---	---	---
Freezing Point	°C	■ -35	---	---	---



CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Red	---	---	---

WASTE MANAGEMENT

61 BROAD AVE.
 FAIRVIEW, NJ
 US 07022
 Contact: ART D'ALESIO
 adalesio@wm.com
 T: (201)832-8124
 F:

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: WASFAINJ
Unique No: 10858373
Signed: Jonathan Hester
Report Date: 05 Feb 2024



CONSTRUCTION EQUIPMENT




VOLVO GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

