

# CONSTRUCTION EQUIPMENT X59145 VOLVO L50H 320062 - REAR AXLE



Sample No: VCP441134

Oil Type: TRANSAXLE OIL SAE 75W80

**Job No:** X59145

SAMPLE	INFORMATION			
Sample Number	<u>-</u>	VCP441134	VCP384640	 
Sample Date		29 Jan 2024	11 Nov 2022	 
Machine Hours		2970	2496	 
Oil Hours		2970	0	 
Oil Changed		Changed	N/A	 
Sample Status		ABNORMAL	SEVERE	 
VOLVO	DITION			
OIL CON		<u> </u>		
Visc @ 40°C	cSt	<b>60.5</b>	<b>49.2</b>	 
VOLVO				
CONTAN	MINATION			
Water	%	<b>△</b> 0.215	2.58	 
Silicon		■ 27	2.38	 
Sodium	ppm	<b>0</b>	□ 13	 
Potassium	ppm	■3	0	 
FOLASSIUITI	ppm	3		 
VOLVO				
<b>WEAR</b> N	METALS			
Iron	ppm	■88	■123	 
Copper	ppm	<b>7</b>	<b>1</b> 1	 
Lead	ppm	<b>0</b>	<b>2</b>	 
Tin	ppm	■0	<b>3</b>	 
Aluminum	ppm	<b>2</b>	<b>4</b>	 
Chromium	ppm	<b>■</b> <1	_2	 
Molybdenum	ppm	<b>0</b>	<b>-</b> <1	 
Nickel	ppm	<b>6</b>	9	 
Titanium	ppm	<1	<1	 
Silver	ppm	0	0	 
Manganese	ppm	<b>1</b>	<b>5</b>	 
Vanadium	ppm	0	0	 
ADDITIV	/ES			
Calcium	ppm	■3363	□3510	 
Magnesium	ppm	<b>15</b>	21	 
Zinc	ppm	<b>1415</b>	<b>□</b> 1571	 
Phosphorus	ppm	<b>1301</b>	1289	 
Barium	ppm	■8	<b>0</b>	 
Boron	ppm	<b>73</b>	<b>114</b>	 



### SCOTT EQUIPMENT COMPANY LLC - Saint Rose

PO BOX 997
SAINT ROSE, LA
US 70087
Contact: DANA FOSHEE
dfoshee@scottcompanies.com
T: (504)461-0961
F: (504)461-0970

#### Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is a light concentration of water present in the oil. The condition of the oil is acceptable for the time in service.

Depot:SCOSAIUnique No:10859950Signed:Jonathan HesterReport Date:05 Feb 2024



## **CONSTRUCTION EQUIPMENT**





